



Top 10 Reasons to Fail an Annual Fire Marshal Inspection:

- 1.) Fire extinguishers are past due for annual certification, out of service or missing.
- 2.) Exit lights and emergency lights are not working.
- 3.) Extension cords used in lieu of permanent wiring.
- 4.) Storage too close to sprinkler heads or ceiling and storage too close to electrical panels.
- 5.) Combustible materials being too close to the hot water heater or the heating unit.
- 6.) Loose electrical wiring, gaps where breakers are missing in the breaker panel and open electrical boxes
- 7.) Sprinkler systems, fire alarm systems and kitchen hood suppression systems past due for annual certification.
- 8.) Locked or blocked exits.
- 9.) Missing or obstructed address or suite numbers.
- 10.) Fire lanes need restriping.